



## **AP 100/50 M**

One machine with unique features allow the operator to clean multiple surfaces easily and safely while increasing productivity, saving time, and reducing labor costs.



## AP 100/50 M

### Technical data

Max. Pressure	psi	100 / 900
Flow rate	gal/min	0,66 / 1,25
Voltage	V	110
Weight without accessories	lb	210
Dimensions (L x W x H)	in	36 x 24,75 x 43

### Equipment

Switch-CHEM-System

-